

CORNER HISTORY:

CORNER FILE CODE:
T6S-R9W-L-13

ORIGINAL USPLS SURVEY: Corner established by Jacob Fowler, Dec., 1805 (missing notes).

COUNTY SURVEYOR'S BOOKS: Book 1 P. 30- Isaac Adams WCS Sept. 1, 1854 "Wood Post".

Book 1 P. 96: John C. Frory WCS Mor. 30, 1858 mentions "Former survey by Adams" along Section Line. OTHER SURVEYS AND PLATS:

"Corner Code System" card includes an undated [ref. to](#) a 1" solid LP. A 5/8" [LP. is](#) shown on the 1987 plot of Westwood Section "C" Part

3.

A 3/4" Rebar was found and tied in to the Telephone Road Route Survey (Bernardin-Lochmueller & Assoc.) 2002.

VERIFICATION OF CORNER POSITION: September, 2002: The 3/4" rebar shown was found in place. Only one of the reference ties shown on the Corner Code System card was found; the distance measured was 0.49' short of record (possibly due to displacement of the power pole). The measured distance to the center seam of Idaho Drive agreed reasonably well with plat dimensions from Westwood Section "C" Part 3.

Perry E. Jones 9/9/02